


PM Warranty Process Flow Chart



- All deviations identified at final inspection must be repaired by CLA
- If the roof receives a rating of 5 or below, PM must re-inspect the roof after the repairs are completed and CLA will be charged a re-inspection fee to be paid prior to re-inspection.
- See Inspection Procedures for further details.
- Roof warranties are only available to Pre-Approved Certified Licensed Applicator's (CLA's)

Find out more at pmsilicone.com/warranty-program.